


Source: Prestolite Leece-Neville Heavy Duty Systems
Bulletin No: TSB-1228 **Date:** August 08, 2023
Models: BLD / BLP4000
Subject: Terminal identification when replacing Remy 40Si



techservice@prestolite.com

This document is to identify terminals between Prestolite BLD / BLP4000 to Remy 40Si alternators.



Note: Two positive and negative connections on BLD / BLP4000 series alternators are common connections.
Use the connection that works best in your application.

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Technical Service: techservice@prestolite.com

