








Group:	AC203RB Alternators	Notes:
Form:	SP4015_AC203RB_Series	1. Service parts & kits listing. (AC203RB)
Date:	March 17, 2015 (Rev: 3)	2. Rotor & cover updates.
File:	Service parts list section	3. Rotor updates.








Component View	Front housing	Stator	Rotor	Rear housing	Rectifier	Regulator	Pulley retention kit
							
Part number	1	2	3	4	5	6	7
<b>1286B000</b> <b>880703BZ</b>	6270-511	6332-A1469	6332-A1388	6270-508	6270-653	1861850	6270-571B
<b>1286B010</b> <b>880712BZ</b>	6270-511	6332-A1471	6332-A1388	6270-508	6270-653	1861850	6270-571B
<b>1286B500</b> <b>880704BZ</b>	6270-511	6332-A1470	6332-A1388	6270-508	6270-653	1861850	6270-571B
<b>1286B510</b> <b>880725BZ</b>	6270-511	6332-A1472	6332-A1388	6270-508	6270-653	1861850	6270-571B
<b>1286B560</b> <b>880731BZ</b>	6270-511	6332-A1480	6332-A1388	6270-508	6270-653	1861850	6270-571B
<b>1286B570</b>	6270-511	6332-A1479	6332-A1388	6270-508	6270-653	1861850	6270-571B
<b>1286B580</b>	6270-586A	6332-A1479	6332-A1492	6270-591	6270-653	1861850	6270-571B
<b>1286B590</b>	6270-598	6332-A1479	6332-A1512	6270-591	6270-653	1861850	6270-571B
<b>1286B630</b>	6270-511	6332-A1470	6332-A1388	6270-508	6270-653	1861850	6270-571B
<b>1286B640</b>	6270-586A	6332-A1479	6332-A1512	6270-591	6270-653	1861A726	6270-571B
<b>1286B670</b>	6270-586A	6332-A1505	6332-A1492	6270-591	6270-653	1861850	6270-571B
<b>1286B680</b>	6270-598	6332-A1480	6332-A1512	6270-591	6270-653	1861850	6270-571B
<b>1286B690</b>	6270-598	6332-A1506	6332-A1499	6270-591	6270-653	1861850	6270-571K
<b>1286B710</b>	6270-586A	6332-A1505	6332-A1512	6270-591	6270-653	1861A726	6270-571B
<b>1286B720</b>	6270-586A	6332-A1479	6332-A1512	6270-591	6270-653	1861850	6270-571B
<b>1286B730</b>	6270-586A	6332-A1505	6332-A1512	6270-591	6270-653	1861850	6270-571B
<b>1286B740</b>	6270-675A	6332-A1506	6332-A1508	6270-591	6270-653	1861850	6270-571K
<b>1286B750</b>	6270-598	6332-A1470	6332-A1512	6270-591	6270-653	1861850	6270-571B
<b>1286B760</b>	6270-598	6332-A1479	6332-A1512	6270-591	6270-653	1861850	6270-571B

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at:

Prestolite Electric Ltd  
Unit 48, The Metropolitan Park  
12-16 Bristol Road, Greenford,  
Middlesex  
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000  
Fax: +44 (0) 20 8575 9575  
[eu\\_info@prestolite.com](mailto:eu_info@prestolite.com)

Group:	AC203RB Alternators	Notes:
Form:	SP4015_AC203RB_Series	2. Rotor & cover updates.
Date:	March 18, 2015 (Rev: 4)	3. Rotor updates.
File:	Service parts list section	4. Slip ring updates.







Component View	Fan	Bearing kit	Brush box / housing assembly	Brush assembly	Slip ring	Stauffer lubricator	Cover & duct kit
							
Part number	8	9	10	11	12	13	14
<b>1286B000</b> <b>880703BZ</b>	6360-254	6270-571A	6270-571D	6270-495	6019-464	5886-242	6270-571C
<b>1286B010</b> <b>880712BZ</b>	6360-254	6270-571A	6270-571D	6270-495	6019-464	5886-242	6270-571C
<b>1286B500</b> <b>880704BZ</b>	6360-254	6270-571A	6270-571D	6270-495	6019-464	5886-242	6270-571C
<b>1286B510</b> <b>880725BZ</b>	6360-254	6270-571A	6270-571D	6270-495	6019-464	5886-242	6270-571C
<b>1286B560</b> <b>880731BZ</b>	6360-254	6270-571A	6270-571D	6270-495	6019-464	5886-242	6270-571C
<b>1286B570</b>	6360-254	6270-571H	6270-571D	6270-495	6019-464	5886-242	6270-571C
<b>1286B580</b>	6270-657	6270-571L	6270-571D	6270-495	6360-431	-	6270-571C
<b>1286B590</b>	6360-254	6270-571J	6270-571D	6270-495	6270-687	-	6270-571C
<b>1286B630</b>	6360-254	6270-571H	6270-571D	6270-495	6019-464	5886-242	6270-571C
<b>1286B640</b>	6270-657	6270-571L	6270-571D	6270-495	6270-687	-	6270-571R
<b>1286B670</b>	6270-657	6270-571L	6270-571D	6270-495	6360-431	-	6270-571C
<b>1286B680</b>	6360-254	6270-571J	6270-571D	6270-495	6270-687	-	6270-571C
<b>1286B690</b>	6360-254	6270-571J	6270-571D	6270-495	6360-431	-	6270-571M
<b>1286B710</b>	6270-657	6270-571L	6270-571D	6270-495	6270-687	-	6270-571R
<b>1286B720</b>	6270-657	6270-571L	6270-571D	6270-495	6270-687	-	6270-571R
<b>1286B730</b>	6270-657	6270-571L	6270-571D	6270-495	6270-687	-	6270-571R
<b>1286B740</b>	6270-657	6270-571L	6270-571D	6270-495	6360-431	-	6270-571M
<b>1286B750</b>	6360-254	6270-571J	6270-571D	6270-495	6270-687	-	6270-571C
<b>1286B760</b>	6360-254	6270-571J	6270-571D	6270-495	6270-687	-	6270-571C

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at:

Prestolite Electric Ltd  
Unit 48, The Metropolitan Park  
12-16 Bristol Road, Greenford,  
Middlesex  
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000  
Fax: +44 (0) 20 8575 9575  
[eu\\_info@prestolite.com](mailto:eu_info@prestolite.com)

Group:	AC203RB Alternators	Notes:
Form:	SP4015_AC203RB_Series	2. Rotor & cover updates.
Date:	March 18, 2015 (Rev: 4)	3. Rotor updates.
File:	Service parts list section	4. Slip ring updates.

Component View	Fastener kit	Terminal kit	Deutsch connector kit	Bearing clamp plate	Suppressor / lead assembly	Vehicle connector kit
						
Part number	15	16	17	18	19	20
<b>1286B000</b> <b>880703BZ</b>	6270-571N	6270-571E	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B010</b> <b>880712BZ</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B500</b> <b>880704BZ</b>	6270-571N	6270-571E	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B510</b> <b>880725BZ</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B560</b> <b>880731BZ</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B570</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B580</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B590</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B630</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B640</b>	6270-571N	6270-571E	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B670</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B680</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B690</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B710</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B720</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B730</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B740</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B750</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q
<b>1286B760</b>	6270-571N	6270-571P	6270-571G	6270-326	6220-922	6270-571Q


Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at:

Prestolite Electric Ltd  
Unit 48, The Metropolitan Park  
12-16 Bristol Road, Greenford,  
Middlesex  
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000  
Fax: +44 (0) 20 8575 9575  
[eu\\_info@prestolite.com](mailto:eu_info@prestolite.com)

Group:	AC203RB Alternators	Notes:
Form:	SP4015_AC203RB_Series	2. Rotor & cover updates.
Date:	March 18, 2015 (Rev: 4)	3. Rotor updates.
File:	Service parts list section	4. Slip ring updates.

## Exploded view



**Important:** The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at:

Prestolite Electric Ltd  
Unit 48, The Metropolitan Park  
12-16 Bristol Road, Greenford,  
Middlesex  
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000  
Fax: +44 (0) 20 8575 9575  
[eu\\_info@prestolite.com](mailto:eu_info@prestolite.com)