














Group:	AVi150 Series Alternators	Notes:
Form:	SP4017_AVi150_Series_AM	Rev.11 = Universal regulator fitting fit added.
Date:	March 15, 2023 (Rev: 11)	Rev.10 = AVi150P2x removed. AVi150P1159HP added.
File:	Service parts list section	

Component View	Front housing	Rear housing	Rotor	Stator	Rectifier kit	Regulator	Regulator fitting kit
							
Part number	1	2	3	4	5	6	7
AVi150P1103HP	6530-590	6530-591	6530-583	6530-589	6530-170A	1861924	6530-993
AVi150S1104HP	6530-47	6530-101	6530-583	6530-589	6530-252	1861940	6530-993
AVi150J1106HP	6530-120	6530-123	6530-236	6530-589	6530-252	1861938	6530-993
AVi150S1108HP	6530-143	6530-146	6530-583	6530-589	6530-252	1861938	6530-993
AVi150S1109HP	6530-47	6530-101	6530-583	6530-589	6530-252	1861940	6530-993
AVi150P1110HP	6530-161	6530-164	6530-309	6530-589	6530-252	1861918	6530-993
AVi150S1111HP	6530-143	6530-146	6530-583	6530-589	6530-252	1861940	6530-993
AVi150S1112HP	6530-143	6530-146	6530-583	6530-589	6530-252	1861938	6530-993
AVi150S1114HP	6530-47	6530-101	6530-583	6530-589	6530-252	1861940	6530-993
AVi150S1115HP	6530-47	6530-101	6530-583	6530-589	6530-252	1861940	6530-993
AVi150J1116HP	6530-295	6530-292	6530-583	6530-589	6530-252	1861938	6530-993
AVi150S1121HP	6530-47	6530-101	6530-583	6530-589	6530-252	1861940	6530-993
AVi150P1122HP	6530-590	6530-591	6530-583	6530-589	6530-170A	1861924	6530-993
AVi150J1135HP	6530-120	6530-123	6530-340	6530-589	6530-252	1861940	6530-993
AVi150J1136HP	6530-295	6530-292	6530-583	6530-589	6530-252	1861938	6530-993
AVi150P1159HP	6530-590	6530-591	6530-583	6530-589	6530-170A	1861924	6530-993

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Group:	AVi150 Series Alternators	Notes:
Form:	SP4017_AVi150_Series_AM	Rev.11 = Universal regulator fitting fit added.
Date:	March 15, 2023 (Rev: 11)	Rev.10 = AVi150P2x removed. AVi150P1159HP added.
File:	Service parts list section	

Component View	Front bearing kit	Rear bearing kit	Slip ring cover kit	Rear cover kit	Pulley kit	Through bolt kit
						
Part number	8	9	10	11	12	13
AVi150P1103HP	6530-172A	6530-173D	6530-174A	6530-175C	6524-46	6530-177A
AVi150S1104HP	6530-172A	6530-173D	6530-174A	6530-175B	6530-253A	6530-177A
AVi150J1106HP	6530-172A	6530-173D	6530-174A	6530-175B	6530-253E	6530-177A
AVi150S1108HP	6530-172A	6530-173D	6530-174A	6530-175A	6530-253	6530-177A
AVi150S1109HP	6530-172A	6530-173D	6530-174A	6530-175A	6530-253	6530-177A
AVi150P1110HP	6530-585	6530-173C	6530-586	6530-587	6530-253F	6530-588
AVi150S1111HP	6530-172A	6530-173D	6530-174A	6530-175A	6530-253	6530-177A
AVi150S1112HP	6530-172A	6530-173D	6530-174A	6530-175B	6530-253	6530-177A
AVi150S1114HP	6530-172A	6530-173D	6530-174A	6530-175A	6530-253	6530-177A
AVi150S1115HP	6530-172A	6530-173D	6530-174A	6530-175B	6530-253B	6530-177A
AVi150J1116HP	6530-172A	6530-173D	6530-174A	6530-175B	6530-253D	6530-177A
AVi150S1121HP	6530-172A	6530-173D	6530-174A	6530-175B	6530-253A	6530-177A
AVi150P1122HP	6530-172A	6530-173D	6530-174A	6530-175C	6524-46	6530-177A
AVi150J1135HP	6530-172A	6530-173D	6530-584	6530-175B	6530-253E	6530-177A
AVi150J1136HP	6530-172A	6530-173B	6530-174A	6530-175B	6530-253C	6530-177A
AVi150P1159HP	6530-172B	6530-811	6530-174A	6530-175C	6524-46	6530-177A

Part number	Notes
AVi150P1103HP	Pulley included
AVi150S1104HP	Pulley included
AVi150J1106HP	No pulley
AVi150S1108HP	Pulley included
AVi150S1109HP	Pulley included
AVi150P1110HP	No pulley
AVi150S1111HP	Pulley included
AVi150S1112HP	Pulley included
AVi150S1114HP	Pulley included
AVi150S1115HP	Pulley included
AVi150J1116HP	No pulley
AVi150S1121HP	Pulley included
AVi150P1122HP	No pulley
AVi150J1135HP	No pulley
AVi150J1136HP	Pulley included
AVi150P1159HP	Pulley included


Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Prestolite Electric Ltd
Unit 48, The Metropolitan Park
12-16 Bristol Road, Greenford,
Middlesex
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000
Fax: +44 (0) 20 8575 9575
eu_info@prestolite.com

Group:	AVi150 Series Alternators	Notes:
Form:	SP4017_AVi150_Series_AM	Rev.11 = Universal regulator fitting fit added.
Date:	March 15, 2023 (Rev: 11)	Rev.10 = AVi150P2x removed. AVi150P1159HP added.
File:	Service parts list section	

EXPLODED VIEW & KIT IDENTIFICATION



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Prestolite Electric Ltd
Unit 48, The Metropolitan Park
12-16 Bristol Road, Greenford,
Middlesex
UB6 8UP, United Kingdom

Tel: +44 (0) 20 8231 1000
Fax: +44 (0) 20 8575 9575
eu_info@prestolite.com