

Source: Prestolite Electric Leece Neville Heavy Duty Systems-Arcade, NY

Bulletin No: TWB-0054 **Date:** November 5, 2021

Models: A1743D_A1744H

Subject: Wiring Diagram



techservice@prestolite.com

+1 (844) 492-4062

+44 20 8231 1000




Anschlussdiagramm für A1743D und A1744H

Der Generator verfügt einen direkten Erdanschluss
AC/W und Feld2 sind optionale Anschlussmöglichkeiten
Lamp: 3W max.

Drehmoment Vorgaben für die Anschlüsse

| | |
|---------------------|----------|
| B+ | 7 – 9 Nm |
| B-, D+, S, IG, W, F | 5 – 6 Nm |



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

North & South America: Phone: +1 (844) 492-4062 | techservice@prestolite.com

Europe: Phone: +44 20 8231 1000 | techservice@prestolite.com

