

**Source:** Leece-Neville Heavy Duty Systems Division  
**Bulletin No:** TSB-1230 **Date:** October 2, 2023  
**Models:** BLD3000 series  
**Subject:** Terminal Id. from BLD3000 series to BLD4114M




techservice@prestolite.com


**Various BLD3000 series 24V 140A can be replaced by the BLD4114M alternator.  
 See matrix below.**

This document will help identify terminal location variances.

Wire termination and routing may require changes.

Amperage upgrades available: BLD4108M (24V 185A), BLD4102M (24V 250A).

Model #	Voltage	Amperage	Substitute	Model #	Amperage
BLD3314 BLD3314GH BLD3314GH-1 (PC3817) BLD3314HC (3975140) BLD3388HC (4372404)	24	140		BLD4114M	140



**Important:** The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at [www.prestolite.com](http://www.prestolite.com), or contact our technical service department at:



**Technical Service:** [techservice@prestolite.com](mailto:techservice@prestolite.com)